
LIGHT= 8.89
TEMP= 27°C
VOLTAGE=8.8 V
CURRENT=23.3 A


HelloHelloHelloH


com15 - HyperTerminal
File Edit View Call Transfer Help
Untitled - Notepad
File Edit Format View Help
temp=read adc();
putch(temp);

Subroutine for transmitting data through RS232:
void putch(unsigned char c)
{
while(!TXIF) //set when register is
empty
{
// clear usart errors inline;
CLRWDT();
}
TXREG=c;
delay(60);
}